

## PRODUCT SAFETY NOTICE

### SUBJECT: RS-670 BLC Plug Replacement

#### Affected Units:

- R-600 1<sup>st</sup> stages with S/N's between:  
UR600022 - UR600029  
UR600031 - UR600103  
UR600637 - UR600676  
UR600708 - UR600716  
UR600737 - UR600776

TUSA was recently informed about the possible loosening of the BLC plug on the R-600 1<sup>st</sup> stage. There is a slight chance this may cause a high-pressure leak creating an unstable intermediate pressure. Immediate return of the units is requested.

To locate the 1<sup>st</sup> stage serial number, please refer to the image below and/or to the RS-670 product box.



#### Action:

- **DEALERS:** Contact customers who have purchased RS-670 units and request return of their units to your store for inspection.
- All owners and dealers with RS-670 units within the above listed range are requested to return them to TUSA for replacement under warranty.
- Contact TUSA Customer Service at 1-800-482-2282 to request a RMA# and issuance of a return freight call-tag.
- This service is covered under warranty.

TUSA will service the affected units and return within approximately 7-10 business days after receipt.

If you have any further questions, please contact TUSA at 800-482-2282 or [info@tusa.com](mailto:info@tusa.com).